











note missing rib>

The image shows the interior of a wooden boat hull during construction. The hull is formed by numerous curved wooden ribs that follow the shape of the boat. Two long, straight wooden beams are positioned vertically inside the hull, likely to provide structural support. A text overlay with an arrow points to a gap between two ribs, indicating a missing rib.





